




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6251																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7738950007																								
Technician Name :	Anil Yadav	Technician Mobile :	8090436743																						
Ticket Type :	New Installation	Date & Time :	26-08-2022 12:10:22																						
Vendor Details :																									
Company Name/Client Name :	Damji Shamji - Mahavir Kalpavruksh J Wing	Customer's Mobile :	7738950007	Name :	Vishal Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	cabling installation																								
Technician Comment :	Cabling (4+1) = 334mtr. one old camera installed back side Gate.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Cabling (4+1) = 334mtr. one old camera installed back side Gate.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-08-2022 05:56:37</td><td>Anil Yadav</td><td>Completed</td><td>Cabling (4+1) = 334mtr. one old camera installed back side Gate.</td><td></td></tr><tr><td>26-08-2022 12:10:39</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>26-08-2022 12:10:22</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-08-2022 05:56:37	Anil Yadav	Completed	Cabling (4+1) = 334mtr. one old camera installed back side Gate.		26-08-2022 12:10:39	Anil Yadav	New		-	26-08-2022 12:10:22	Anil Yadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-08-2022 05:56:37	Anil Yadav	Completed	Cabling (4+1) = 334mtr. one old camera installed back side Gate.																						
26-08-2022 12:10:39	Anil Yadav	New		-																					
26-08-2022 12:10:22	Anil Yadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-06-2022 11:23:04</td><td>Javed Bhaladar</td><td>1) camera not working 2)Few camera angle setting work pending req 2 person in the side 3) camera reinstallation pending 4) 2 camera new installation pending Client req recalling with pipe 72/73mtr cable pipe damage building plaster time</td></tr><tr><td>22-02-2022 01:45:32</td><td>Neeraj Chauhan</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	08-06-2022 11:23:04	Javed Bhaladar	1) camera not working 2)Few camera angle setting work pending req 2 person in the side 3) camera reinstallation pending 4) 2 camera new installation pending Client req recalling with pipe 72/73mtr cable pipe damage building plaster time	22-02-2022 01:45:32	Neeraj Chauhan												
Date Time	Technician Name	Remark																							
08-06-2022 11:23:04	Javed Bhaladar	1) camera not working 2)Few camera angle setting work pending req 2 person in the side 3) camera reinstallation pending 4) 2 camera new installation pending Client req recalling with pipe 72/73mtr cable pipe damage building plaster time																							
22-02-2022 01:45:32	Neeraj Chauhan																								