

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9566																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8108008855																			
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																
Ticket Type :	New Installation	Date & Time :	18-09-2023 10:08:45																	
Vendor Details :																				
Company Name/Client Name :	Varadvinayak Developers	Customer's Mobile :	8108008855	Name :	Vishram Gori															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	2 new cameras installation with cabling																			
Technician Comment :	2 camera cebaling done and camera insttal done wark camleted and cwbling use 137 miter and riten cebal 47 miter																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 camera cebaling done and camera insttal done wark camleted and cwbling use 137 miter and riten cebal 47 miter																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-09-2023 03:44:23</td><td>Shiva Meena</td><td>Completed</td><td>2 camera cebaling done and camera insttal done wark camleted and cwbling use 137 miter and riten cebal 47 miter</td><td></td></tr><tr><td>18-09-2023 10:08:53</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-09-2023 03:44:23	Shiva Meena	Completed	2 camera cebaling done and camera insttal done wark camleted and cwbling use 137 miter and riten cebal 47 miter		18-09-2023 10:08:53	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
18-09-2023 03:44:23	Shiva Meena	Completed	2 camera cebaling done and camera insttal done wark camleted and cwbling use 137 miter and riten cebal 47 miter																	
18-09-2023 10:08:53	Shiva Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-09-2023 04:27:07</td><td>Atique Salmani</td><td>2 cameras servey done 1 need to mane gate and second is peepal tree cable approx 150 meter</td></tr><tr><td>23-08-2023 01:58:44</td><td>Ravi Rajbhar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	12-09-2023 04:27:07	Atique Salmani	2 cameras servey done 1 need to mane gate and second is peepal tree cable approx 150 meter	23-08-2023 01:58:44	Ravi Rajbhar							
Date Time	Technician Name	Remark																		
12-09-2023 04:27:07	Atique Salmani	2 cameras servey done 1 need to mane gate and second is peepal tree cable approx 150 meter																		
23-08-2023 01:58:44	Ravi Rajbhar																			